CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57627

ion Constant: 97.6

Calibration Multiplier: -10.25

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and ion multiplier. Recalibration is recommended every two years.

Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebra
Phone: 402-467-3576 ● FAX: 402-467-28
Toll-free 1-800-447-3576 (U.S. & Canada)
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57628

tion Constant: 88.0

Calibration Multiplier: -11.36

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and
tion multiplier. Recalibration is recommended every two years.

Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebra
Phone: 402-467-3576 ● FAX: 402-467-28
Toll-free 1-800-447-3576 (U.S. & Canada
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57629

tion Constant: 89.1

Calibration Multiplier: -11.22

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-28
Toll-free 1-800-447-3576 (U.S. & Canada
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57630

tion Constant: 92.8

Calibration Multiplier: -10.78

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-28
Toll-free 1-800-447-3576 (U.S. & Canada
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

lel Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57631

ation Constant: 89.5

Calibration Multiplier: -11.17

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-2
Toll-free 1-800-447-3576 (U.S. & Canad
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

lel Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57632

ation Constant: 91.0

Calibration Multiplier: -10.99

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-2
Toll-free 1-800-447-3576 (U.S. & Canad
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57633

ation Constant: 88.5

Calibration Multiplier: -11.30

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-28
Toll-free 1-800-447-3576 (U.S. & Canada
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57634

ation Constant: 83.2

Calibration Multiplier: -12.02

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-28
Toll-free 1-800-447-3576 (U.S. & Canada
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57636

ation Constant: 88.7

Calibration Multiplier: -11.27

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-28
Toll-free 1-800-447-3576 (U.S. & Canada
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

lel Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57637

ation Constant: 91.2

Calibration Multiplier: -10.96

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-2
Toll-free 1-800-447-3576 (U.S. & Canad
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57638

tion Constant: 95.8

Calibration Multiplier: -10.44

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences
4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-28
Toll-free 1-800-447-3576 (U.S. & Canada
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57639

tion Constant: 95.3

Calibration Multiplier: -10.49

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences
4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-28
Toll-free 1-800-447-3576 (U.S. & Canada
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57640

ation Constant: 98.4

Calibration Multiplier: -10.16

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-28
Toll-free 1-800-447-3576 (U.S. & Canada
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY57641

ation Constant: 93.4

Calibration Multiplier: -10.71

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: June 8, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-2
Toll-free 1-800-447-3576 (U.S. & Canad
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

lel Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY58058

ation Constant: 92.1

Calibration Multiplier: -10.86

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: August 7, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-2
Toll-free 1-800-447-3576 (U.S. & Canad
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY58059

ation Constant: 88.3

Calibration Multiplier: -11.33

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: August 7, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-2
Toll-free 1-800-447-3576 (U.S. & Canad
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY58060

ation Constant: 93.2

Calibration Multiplier: -10.73

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: August 7, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-28
Toll-free 1-800-447-3576 (U.S. & Canada
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

lel Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY58061

ation Constant: 87.5 Calibration Multiplier: -11.43

microamps per 1000 watts m-2 Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: August 7, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Neb
Phone: 402-467-3576 ● FAX: 402-467-2
Toll-free 1-800-447-3576 (U.S. & Canad
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

lel Number: **LI-200SZ PYRANOMETER SENSOR**

l Number: PY58062

ation Constant: 92.3

Calibration Multiplier: -10.83

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and ation multiplier. Recalibration is recommended every two years.

f Calibration: August 7, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Neb
Phone: 402-467-3576 ● FAX: 402-467-2
Toll-free 1-800-447-3576 (U.S. & Canad
E-mail: envsales@licor.com
www.licor.com

CERTIFICATE OF CALIBRATION

el Number: **LI-200SZ PYRANOMETER SENSOR**

Number: PY58063

ation Constant: 92.1

Calibration Multiplier: -10.86

microamps per 1000 watts m-2

Units: watts m-2 per microamp

consult the instruction manual for further information on the calibration constant and tion multiplier. Recalibration is recommended every two years.

f Calibration: August 7, 2007

Caron Deschane

LI-COR®
Biosciences

4421 Superior Street ● P.O. Box 4425 ● Lincoln, Nebr
Phone: 402-467-3576 ● FAX: 402-467-28
Toll-free 1-800-447-3576 (U.S. & Canada
E-mail: envsales@licor.com
www.licor.com